New BMS Safety Feature (Power-Up)



Battery As Received: OFF



Step 1: Install the Round LCD Display

Step 2: Press(Latch) the BMS Power Button



New BMS Safety Feature (Power-Up)

Note That the LCD Display and the Red L.E.D. is Illuminated, but, the Contactor Has Not Latched (Terminals are Safe)



Step 3: Press the RESET Button for 1 Second and Notice the Contactor Latches. The Battery is Now in the LIVE or ON State



Power Cycle OFF, Leaves SOC "ON": Press the Reset Button for <u>5 Full Seconds</u> Then Release. Battery is SAFE for Terminal Voltage



Storage MODE: Power-Down the SOC Gage and the Battery for Long Term Storage: Press-Release the MAIN POWER Switch (to UP Position)

